



TRUE

True, there is no drying time. Fastening is instantaneous. It provides for continuity of production and increased productivity.

- As adhesive tape is pressure sensitive, the initial adhesion provides sufficient performance for handling and processing the joints made
- However, to obtain final performance and assess the strength of bonded substrates, a 48 to 72 hour delay is often required.